

UNCLASSIFIED



## **CISCO IOS XR ROUTER STIG REVISION HISTORY**

**24 October 2024**

**Developed by DISA for the DOD**

UNCLASSIFIED

| REVISION HISTORY                     |  |                 |
|--------------------------------------|--|-----------------|
| Document Revised                     | Description of Change  | Release Date    |
| - Cisco IOS XR Router NDM STIG, V3R1 | <b>Cisco IOS XR Router NDM STIG, V3R2:</b><br>- CISC-ND-000470 - Updated requirement to address the call home feature.   | 24 October 2024 |
| - Cisco IOS XR Router RTR STIG, V3R1 | <b>Cisco IOS XR Router RTR STIG, V3R2:</b><br>- CISC-RT-000010 - Updated Check text to include VRF.<br>- CISC-RT-000050 - Updated MD5 note in check text.<br>- CISC-RT-000320 - Updated Discussion.  |                 |
| - Cisco IOS XR Router NDM STIG, V2R5 | <b>Cisco IOS XR Router NDM STIG, V3R1:</b><br>- CISC-ND-000140, CISC-ND-001000, CISC-ND-001030 - Updated based on NIST SP 800-53 Rev. 5 changes.   | 24 July 2024    |
| - Cisco IOS XR Router RTR STIG, V2R4 | <b>Cisco IOS XR Router RTR STIG, V3R1:</b><br>- CISC-RT-000400, CISC-RT-000580, CISC-RT-000590, CISC-RT-000630, CISC-RT-000640, CISC-RT-000650, CISC-RT-000670, CISC-RT-000950 - Updated based on NIST SP 800-53 Rev. 5 changes.<br><br>- Because this is a major revision, version numbers were incremented to the next whole number.<br>- Rule numbers updated throughout due to changes in content management system. |                 |
| - Cisco IOS XR Router NDM STIG, V2R4 | <b>Cisco IOS XR Router NDM STIG, V2R5:</b><br>- CISC-ND-000470 - Added call home to check text and no call home to fix text.   | 24 January 2024 |
| - Cisco IOS XR Router RTR STIG, V2R3 | <b>Cisco IOS XR Router RTR STIG, V2R4:</b><br>- CISC-RT-000020, CISC-RT-000030, CISC-RT-000040 - Merged into CISC-RT-000050.<br>- CISC-RT-000050 - Updated requirement to reflect OSPF and BGP keychains.  | 25 October 2023 |
| - Cisco IOS XR Router NDM STIG, V2R3 | <b>Cisco IOS XR Router NDM STIG, V2R4:</b><br>- CISC-ND-000290 - Updated the check to reference interface ACLs.<br>- CISC-ND-000720 - Rule number updated due to changes in content management system.   |                 |

| REVISION HISTORY |  |              |
|------------------|--|--------------|
| Document Revised | Description of Change  | Release Date |
|                  | - Revision History format for multipart STIGs revised to ensure clarity in the versioning. |              |

| REVISION HISTORY |                                  |   |               |
|------------------|----------------------------------|---|---------------|
| Revision Number  | Document Revised                 | Description of Change   | Release Date  |
| V2R5             | - Cisco IOS XR Router STIG, V2R4 | <b>Cisco IOS XR Router RTR STIG, V2R3:</b><br>- CISC-RT-000760, CISC-RT-000770 - Removed reference to QOS DODIN Technical Profile.<br><br><b>Cisco IOS XR Router NDM STIG, V2R3:</b><br>- No change in this quarter.  | 26 July 2023  |
| V2R4             | - Cisco IOS XR Router STIG, V2R3 | <b>Cisco IOS XR Router NDM STIG, V2R3:</b><br>- CISC-ND-000720 - Changed idle timeout to five minutes.<br>- CISC-ND-001370 - Changed requirement to utilize redundant authentication servers. Updated CCI.<br>- CISC-ND-001450 - Changed requirement to utilize redundant syslog servers. Updated CCI.<br>- Rule numbers updated throughout due to changes in content management system.<br><br><b>Cisco IOS XR Router RTR STIG, V2R2:</b><br>-No change in this quarter. | 07 June 2023  |
| V2R3             | - Cisco IOS XR Router STIG, V2R2 | <b>Cisco IOS XR Router RTR STIG, V2R2:</b><br>- CISC-RT-000040 - Updated check and fix for BGP TCP-AO.<br>- CISC-RT-000080 - Removed and addressed in the NDM STIG.<br>- CISC-RT-000235 - Added missing finding statement.<br>- Rule Keys updated due to changes in content management system.  | 27 April 2023 |
| V2R2             | - Cisco IOS XR Router STIG, V2R1 | <b>Cisco IOS XR Router NDM STIG, V2R2:</b><br>CISC-ND-000490 - Updated vulnerability discussion to allow secure network location for 'break glass' passwords.   | 23 April 2021 |

| REVISION HISTORY |                                  |  |                 |
|------------------|----------------------------------|--|-----------------|
| Revision Number  | Document Revised                 | Description of Change  | Release Date    |
| V2R1             | - Cisco IOS XR Router STIG, V1R4 | <p><b>Cisco IOS XR Router NDM STIG, V2R1:</b></p> <ul style="list-style-type: none"> <li>- DISA migrated the Cisco IOS XR Router NDM STIG to a new content management system. The new content management system renumbered all Groups (V-numbers) and Rules (SV-numbers). With the new Group and Rule numbers, DISA incremented the version number from V1R4 to V2R1.</li> <li>- CISC-ND-000140 - Updated check and fix to include log-input on deny statement.</li> <li>- CISC-ND-001280 - Removed requirement.</li> </ul> <p><b>Cisco IOS XR Router RTR STIG, V2R1:</b></p> <ul style="list-style-type: none"> <li>- CISC-RT-000020 - Updated vulnerability discussion to clarify the requirement.</li> <li>- CISC-RT-000080 - Updated check to clarify the requirement.</li> <li>- CISC-RT-000235 - Added requirement to enable IPv4 and IPv6 CEF.</li> <li>- CISC-RT-000236 - Added requirement to set hop limit to at least 32 for IPv6 stateless auto-configuration deployments.</li> <li>- CISC-RT-000237 - Added requirement to prohibit use of IPv6 Site Local addresses.</li> <li>- CISC-RT-000391 - Added requirement to suppress IPv6 Router Advertisements at external interfaces.</li> <li>- CISC-RT-000392 - Added requirement to drop IPv6 undetermined transport packets.</li> <li>- CISC-RT-000393 - Added requirement to drop IPv6 packets with a Routing Header type 0, 1, or 3-255.</li> <li>- CISC-RT-000394 - Added requirement to drop IPv6 packets containing a Hop-by-Hop header with invalid option type values.</li> <li>- CISC-RT-000395 - Added requirement to drop IPv6 packets containing a Destination Option header with invalid option type values.</li> <li>- CISC-RT-000396 - Added requirement to drop IPv6 packets containing an extension header with the Endpoint Identification option.</li> </ul> | 23 October 2020 |

| REVISION HISTORY |                                  |  |              |
|------------------|----------------------------------|--|--------------|
| Revision Number  | Document Revised                 | Description of Change  | Release Date |
|                  |                                  | <ul style="list-style-type: none"> <li>- CISC-RT-000397 - Added requirement to drop IPv6 packets containing the NSAP address option within Destination Option header.</li> <li>- CISC-RT-000398 - Added requirement to drop IPv6 packets containing a Hop-by-Hop or Destination Option extension header with an undefined option type.</li> </ul>  |              |
| V1R4             | - Cisco IOS XR Router STIG, V1R3 | <p><b>Cisco IOS XR Router NDM STIG, V1R4:</b></p> <ul style="list-style-type: none"> <li>- V-96497 - Mapped to SRG-APP-000516-NDM-000350.</li> <li>- V-96501 - Mapped to SRG-APP-000516-NDM-000351.</li> <li>- V-96373, V-96375, V-96377, V-96385, V-96387, V-96389, V-96399, V-96401, V-96405, V-96409, V-96411, V-96415, V-96417, V-96419, V-96423, V-96425, V-96427, V-96429, V-96431, V-96435, V-96437, V-96439, V-96441, V-96445, V-96455, V-96457, V-96459, V-96461, V-96469, V-96471, V-96479, V-96481, V-96485, V-96487, V-96489, V-96493, V-96499 - Removed Requirements.</li> </ul> <p><b>Cisco IOS XR Router RTR STIG, V1R4:</b></p> <ul style="list-style-type: none"> <li>- V-96819 - Changed rule title to PE router.</li> <li>- V-96679 - Remapped to SRG-NET-000230-RTR-000001.</li> <li>- V-96681 - Remapped to SRG-NET-000230-RTR-000003.</li> <li>- V-96691 - Remapped to SRG-NET-000131-RTR-000083.</li> <li>- V-96725 - Remapped to SRG-NET-000205-RTR-000014.</li> <li>- V-96733 - Remapped to SRG-NET-000205-RTR-000015.</li> <li>- V-96757 - Remapped to SRG-NET-000362-RTR-000124.</li> <li>- V-96759 - Remapped to SRG-NET-000230-RTR-000002.</li> <li>- V-96813 - Remapped to SRG-NET-000205-RTR-000016.</li> </ul> | 24 July 2020 |

| REVISION HISTORY |                                  |  |                 |
|------------------|----------------------------------|--|-----------------|
| Revision Number  | Document Revised                 | Description of Change  | Release Date    |
| V1R3             | - Cisco IOS XR Router STIG, V1R2 | <b>Cisco IOS XR Router NDM STIG, V1R3:</b><br>- V-96497 - Changed to CAT 1.<br><br><b>Cisco IOS XR Router RTR STIG, V1R3:</b><br>- V-96719 - Provided clarification in the check content.<br>- V-96721 - Corrected typo in discussion.<br>- V-96815, V-96817 - Provided link to GTP QOS document in check and fix content. | 24 April 2020   |
| V1R2             | - Cisco IOS XR Router STIG, V1R1 | <b>Cisco IOS XR Router NDM STIG, V1R2:</b><br>- V-96391 - Removed CISC-ND-000230.<br>- V-96433 - Removed CISC-ND-000840.<br>- V-96491 - Corrected rule title.<br><br><b>Cisco IOS XR Router RTR STIG, V1R2:</b><br>- V-96695 - Corrected typo in check content.<br>- V-96713 - Corrected check and fix content.            | 24 January 2020 |
| V1R1             | - NA                             | - Initial Release.   | 19 July 2019    |