

UNCLASSIFIED



CISCO NX OS SWITCH STIG REVISION HISTORY

24 January 2024

Developed by DISA for the DOD

UNCLASSIFIED

REVISION HISTORY		
Document Revised	Description of Change	Release Date
- Cisco NX OS Switch NDM STIG, V2R6	Cisco NX OS Switch NDM STIG, V2R7: - CISC-ND-000290 - Changed “interface ACLs” to “ACLs” and “log-input parameter” to “log parameter” in check text. - CISC-ND-001130, CISC-ND-001140 - Corrected syntax to meet requirement.	24 January 2024
- Cisco NX OS Switch L2S STIG, V2R2	Cisco NX OS Switch L2S STIG, V2R3: - CISC-L2-000090 - Removed “and host” from check and fix text.	
- Cisco NX OS Switch NDM STIG, V2R5	Cisco NX OS Switch NDM STIG, V2R6: - CISC-ND-000530, CISC-ND-001200, CISC-ND-001210 - Corrected syntax in check text. Removed note in fix text. Updated for style guide compliance. - CISC-ND-000720 - Rule number updated due to changes in content management system. - CISC-ND-001220- Added requirement that was removed. Updated for style guide compliance. - Revision History format for multipart STIGs revised to ensure clarity in the versioning.	25 October 2023

REVISION HISTORY			
Revision Number	Document Revised	Description of Change	Release Date
V2R6	- Cisco NX OS Switch STIG, V2R5	Cisco NX OS Switch L2S STIG, V2R2: - CISC-L2-000190 - Updated check text for correct syntax. Cisco NX OS Switch NDM STIG, V2R5: - No change in this quarter. Cisco NX OS Switch RTR STIG, V2R3: - CISC-RT-000760, CISC-RT-000770 - Removed reference to QOS DODIN Technical Profile.	26 July 2023
V2R5	- Cisco NX OS Switch STIG, V2R4	Cisco NX OS Switch NDM STIG, V2R5: - CISC-ND-000720 - Changed idle timeout to five minutes.	07 June 2023

REVISION HISTORY			
Revision Number	Document Revised	Description of Change	Release Date
		<ul style="list-style-type: none"> - CISC-ND-001370 - Changed requirement to utilize redundant authentication servers. Updated CCI. - CISC-ND-001450 - Changed requirement to utilize redundant syslog servers. Updated CCI. <p>Cisco NX OS Switch RTR STIG, V2R2:</p> <ul style="list-style-type: none"> - No change in this quarter. <p>Cisco NX OS Switch L2S STIG, V2R1:</p> <ul style="list-style-type: none"> - No change in this quarter. 	
V2R4	- Cisco NX OS Switch STIG, V2R3	<p>Cisco NX OS Switch NDM STIG, V2R4:</p> <ul style="list-style-type: none"> - CISC-ND-000250, CISC-ND-001290 - Removed requirement; duplicate of CISC-ND-001260. - CISC-ND-001220 - Removed requirement; default policy meets requirement. - Updated title of STIG in content management system to remove hyphen in NX OS. - Rule Keys updated due to changes in content management system. <p>Cisco NX OS Switch RTR STIG, V2R2:</p> <ul style="list-style-type: none"> - Updated title of STIG in content management system to remove hyphen in NX OS. - Rule Keys updated due to changes in content management system. <p>Cisco NX OS Switch L2S STIG, V2R1:</p> <ul style="list-style-type: none"> - DISA migrated the Cisco NX OS Switch L2S STIG to a new content management system. The new content management system renumbered all Groups (V-numbers) and Rules (SV-numbers). With the new Group and Rule numbers, DISA incremented the version number from V1R1 to V2R1. - Updated title of STIG in content management system to remove hyphen in NX OS. 	27 April 2023

REVISION HISTORY			
Revision Number	Document Revised	Description of Change	Release Date
V2R3	- Cisco NX OS Switch STIG, V2R2	Cisco NX OS Switch NDM STIG, V2R3: - CISC-ND-000150 - Updated Title, Check, and Fix to reflect the correct command.	27 October 2021
V2R2	- Cisco NX OS Switch STIG, V2R1	Cisco NX OS Switch NDM STIG, V2R2: - CISC-ND-000490 - Updated vulnerability discussion to allow secure network location for 'break glass' passwords. - CISC-ND-000150 - Updated the check/fix content for correct 15 minute syntax. - CISC-ND-000140 - Corrected configuration example in check and fix content. Cisco NX OS Switch RTR STIG, V2R1: - DISA migrated the Cisco NX OS Switch RTR STIG to a new content management system. The new content management system renumbered all Groups (V-numbers) and Rules (SV-numbers). With the new Group and Rule numbers, DISA incremented the version number from V1R1 to V2R1. - CISC-RT-000236 - Added requirement to set hop limit to at least 32 for IPv6 stateless auto-configuration deployments. - CISC-RT-000237 - Added requirement to prohibit use of IPv6 Site Local addresses. - CISC-RT-000391 - Added requirement to suppress IPv6 Router Advertisements at external interfaces.	23 April 2021
V2R1	- Cisco NX OS Switch STIG, V1R1	Cisco NX OS Switch NDM STIG, V1R1: - DISA migrated the Cisco NX OS Switch NDM STIG to a new content management system. The new content management system renumbered all Groups (V-numbers) and Rules (SV-numbers). With the new Group and Rule numbers, DISA incremented the version number from V1R1 to V2R1. - CISC-ND-000290 - Added line to fix text for adding 'log' to deny ACLs.	22 January 2021
V1R1	- NA	- Initial Release.	08 May 2020