

UNCLASSIFIED



HEWLETT PACKARD (HP) FLEXFABRIC SWITCH STIG REVISION HISTORY

02 July 2025

Developed by DISA for the DOD

UNCLASSIFIED

REVISION HISTORY		
Document Revised	Description of Change	Release Date
- HP FlexFabric Switch NDM STIG, V1R3	HP FlexFabric Switch NDM STIG, V1R4: - HFFS-ND-000053, HFFS-ND-000054 - Corrected Check and Fix. - HFFS-ND-000055 - Corrected Title, Discussion, and Check and Fix. - HFFS-ND-000056 - Corrected Title and Check and Fix. - HFFS-ND-000057, HFFS-ND-000058, HFFS-ND-000062, HFFS-ND-000063 - Corrected Check. - Rule numbers updated throughout due to changes in the content management system.	02 July 2025

REVISION HISTORY			
Revision Number	Document Revised	Description of Change	Release Date
V1R4	- HP FlexFabric Switch L2S STIG, V1R2 - HP FlexFabric Switch NDM STIG, V1R2 - HP FlexFabric Switch RTR STIG, V1R1	L2S: - V-66053, V-66083 - Removed requirement. NDM: - V-66169, V-66197, V-66239 - Removed requirements. RTR: - V-66105 - Removed requirement. - V-66123 - Mapped to SRG-NET-000362-RTR-000110. - V-66125 - Mapped to SRG-NET-000512-RTR-000012.	24 July 2020
V1R3	- HP FlexFabric Switch NDM STIG, V1R1	NDM: - V-66241 - Corrected check content. The following STIGs were not updated this release: - HP FlexFabric Switch L2S STIG, V1R2 - HP FlexFabric Switch RTR STIG, V1R1	25 October 2019
V1R2	- HP FlexFabric	L2S: - Removed HFFS-L2-000004 requirement.	25 January 2019

REVISION HISTORY			
Revision Number	Document Revised	Description of Change	Release Date
	Switch L2S STIG, V1R1	The following STIGs were not updated this release: - HP FlexFabric Switch NDM STIG, V1R1 - HP FlexFabric Switch RTR STIG, V1R1	
V1R1	- HP FlexFabric Switch L2S STIG	- Initial Release.	09 March 2016
V1R1	- HP FlexFabric Switch NDM STIG	- Initial Release.	26 February 2016
V1R1	- HP FlexFabric Switch RTR STIG	- Initial Release.	26 February 2016